No DeFects 349

	/EATHER CONSENT DECREE ATER TESTING FORM	Page _/ of _/_
Sewershed: Low Level Subsewershed: 3	Company: Savin	Page of
Test Type: Smoke X Dyed Water	Grøund Condition: Dry: Damp: Wet:	Supervisor: George
Manhole ID: <u>250 - 014</u>	Test ID: 1029 -046-02	Salanco Crew: 02 Notifications Made: X
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		
Duilding addresses a	nd locations, defect locations and photogl	apn numbers)
	S. Carey St	
	203	700)
3		
-601le		
1		
10		
Ta l		
The state of the s		
105/4		
5		